




AUTOMOTIVE 2K PAINT SYSTEM

Bare Metal Surfaces



CHECKLIST

- 80-180g & 320-600g Sandpaper
- Wax & Grease Remover
- Clean Rags
- Tack Cloth
- Spray Gun
- Respirator
- Gloves
- Masking Film
- Masking Paper
- Masking Tape
- Filler
- Filling Blades
- Thinners
- Mixing Cups

Contact Versatile Products for professional industry advice

LECHLAR: Colours to be selected from colour chart

CONCEPT: Colours to be selected from No Mix Base. Colours may be automotive
NO MIX/SPIES HECKER BASECOATS require a clear coat of Roberlo 150HS or Spies 8045

NOTE: Any Single Pack Top Coat may also be applied over 2K Primers with 2-5x coats required

